



**Warning Note:**  
 If the US IC RT8258 is used, the components D10 and R55 NOT install!!!!  
 If replace US on IC LMR12010, LMR12007 or MCP16301, you should install components D10 and R55

Replace for RT8258  
 R22 = 95.3k 0805  
 R23 = 18.2k 0805  
 If US IC LMR12010, LMR12007 and MCP16301.  
 R22 = 52.3k  
 R23 = 10k